



2022-01-11

This vehicle, 5YJSA1E53MF430273, was previously damaged, repaired, or has a remaining item that requires a disclosure based on local regulations.

Additional Notes:

This vehicle has had its drive train and HV battery pack replaced with new equipment.

If applicable, attached is the repair order form detailing the completed restorations.

Total Cost of Repair Order: \$5,585.70 (excluding tax)

Repair Order Date:

Buyer acknowledgment and signature: \_\_\_\_\_

Buyer acknowledgment and signature: \_\_\_\_\_