



2025-05-06

This vehicle, 7G2CEHEE7RA028257, was previously damaged, repaired, or has a remaining item that requires a disclosure based on local regulations.

Additional Notes:

This vehicle had additional reinforcement added to the front body casting near the right front wheel by a Tesla Service center.

If applicable, attached is the repair order form detailing the completed restorations.

Total Cost of Repair Order: \$0.00 (excluding tax)

Repair Order Date:

Buyer acknowledgment and signature: _____

Buyer acknowledgment and signature: _____