



This vehicle, 5YJSA1E6XMF430702, has been damaged while in Tesla's possession. Attached is the repair order form detailing the restorations completed.

Total Cost of Repairs: \$806.00 USD

Buyer's acknowledgment and signature: _____