



2024-04-12

This vehicle, 5YJ3E7EB9KF216404, was previously damaged, repaired, or has a remaining item that requires a disclosure based on local regulations.

Additional Notes:

- front bumper replaced

This Vehicle may have been previously repaired by a third party prior to sale by Tesla.

Total Cost of Repair Order: 950.00 CHF (excluding tax)

Buyer acknowledgment and signature: _____

Buyer acknowledgment and signature: _____