



2024-12-23

This vehicle, 7SAXCCE65PF385896, was previously damaged, repaired, or has a remaining item that requires a disclosure based on local regulations.

Additional Notes:

- rear door repaired

This Vehicle may have been previously repaired by a third party prior to sale by Tesla.

Total Cost of Repair Order: 2.000,00 € (excluding tax)

Buyer acknowledgment and signature: \_\_\_\_\_

Buyer acknowledgment and signature: \_\_\_\_\_